

U.S. Steel Clairton Works 400 State Street Clairton, PA 15025-1855



October 20, 1994

Deputy Director Allegheny County Health Department Department of Air Quality 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 841 Chestnut Building Philadelphia, PA 19107 ATTN: Michael Ioff (3AT23)

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Ward Kelsey, Esq.

Department of Justice Department of Environmental Resources Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: Breakdown Report 94-1216

#2 Unit Primary Coolers: #15 & 19 Battery Igniter Flares

USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to W. C. Graeser at 233-1467.

> T. Weber General Manager Coking Operations



NOTICE OF BREAKDOWN OF EQUIPMENT ARTICLE XX - SECTION 202.C

- 1. Breakdown No.: 94-1216
- 2. Date & Time of Breakdown: Date: 10/20/94 Time: 0705 hours
- 3. Company Name: USX Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: #2 Unit Primary Coolers; #15 & 19 Battery Igniter Flares
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: This flaring event did not need to be reported within an hour of occurrence. Per Allegheny County correspondence dated June 8, 1992, flaring events less than 2 minutes are to be summarized and reported on the monthly Process Information Report.

Coke oven gas was flared at the following batteries:

		Start	End	Duration	Flared		
Date	Battery	Time	Time	Min.	Sec.	Yes	No
10/20/94	15	07:10	07:10	O	15	Yes	
10/20/94	19	07:10	07:10*	0	20	Yes	
					and the same of th		

* The cumulative 20 second flare time at #19 Battery occurred intermittently over a 8 minute period.

Flares were activated when the battery coke oven gas suction pressure dropped. A level controller malfunction caused a loss of circulating liquor in the 804 primary cooler. The resulting elevated gas temperature caused a loss of battery coke oven gas suction.

8. Identification of Emissions:

- A. Type(s) (CO, NOX, SO2, Particulates, Hydrocarbons, etc.)
 Released products of combustion of Coke Oven Gas.
- B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). Unknown.
- C. Amount of each type emitted (or likely to be emitted). Light to moderate.

9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

Battery charging operations were suspended. The level controller was replaced and start-up procedures were initiated immediately,

10. Facility back/in preration - Date: 10/20/94 Time: 0808 hours

Signature

_ рате

W. C. Graeser

Senior Environmental Control Engineer Phone: 233-1467